
SITE PLAN NOTES: . "FF" - FINISHED FLOOR ELEVATION 2. "AAG" - AVERAGE ADJACENT GRADE. 3. CROSS HATCH REPRESENTS BUILDING OR FLATWORK TO BE REMOVED. TREE NOTES:
A TORA REVIEW WAS CONDUCTED ON SITE WITH JIM GOBEL ON 12.11.20. THE NOTES FROM THIS MEETING RELATED TO TREE REMOVAL INCLUDE THE FOLLOWING: 1 TREE #151 IS AN IMMINENT HAZARD. REMOVAL IS APPROVED. 2. THE REMOVAL OF TREE #29 WILL BE APPROVED WITHOUT REMEDIATION AS LONG AS THE STRUCTURAL ENGINEER PROVIDES A FORMAL LETTER CONFIRMING THE TREE'S CONTINUED GROWTH WILL BE STRUCTURALLY DAMAGING TO THE HOUSE. THIS LETTER IS INCLUDED IN THE ENGINEER'S PERMIT DRAWINGS. 3. TREE #225 IS DEAD AND HAS BEEN REQUESTED FOR REMOVAL. TREE TABLE: TAG # DIAMETER SPECIES CRZ J CRZ Z CRZ CHINESE TALLOW 21' 10.5' 5.25 21 23" LIVE OAK 11.5' 23' 5.75 22 25" BURR OAK 25' 12.5' 6.25 23 13", 13" MESQUITE 19.5' 9.75' 4.88 27 28" BURR OAK 28' 14' 28 19.5" BURR OAK 19.5 9.75' 4.88 29* 22.5" BURR OAK 22.5 11.25 6.25 149 17", 15' LIVE OAK 24.5 12.25 6.13 151* 21" SPANISH OAK 21' 10.5' 5.25' 225* 17", 14" HACKBERRY 24' 12' HALF CRITICAL ROOT ZONES ARE SHOWN SHADED * IDENTIFIES TREE SLATED FOR REMOVAL.

RECORD CALL BUILDING SETBACK LINE PUBLIC UTILITY EASEMENT P.U.E. FOUND IRON ROD FOUND IRON ROD WITH CAP FIRC FOUND IRON PIPE WATER VALVE œ WATER METER UTILITY POLE/GUY ANCHOR UTILITY LINE – P -WOOD FENCE CHAIN LINK FENCE FINISHED FLOOR ELEVATION FF⊗ TREE, DRIPLINE & NUMBER

REFER TO TREE NOTES FOR ADDITIONAL INFORMATION.

BENCHMARK: ▲
SET TRIANGLE ON CURB
NAVD88 ELEVATION: 598.28'



THESE DRAWINGS ARE COPYRIGHT PROTECTED.

2021

MARCH 4,

4113 LULLWOOD AUSTIN, TEXAS 78722

CHENNELL GILBREATH RESIDENCE

<u>ARCHITECT:</u> SARAH BULLOCK MCINTYRE, AIA

1313 Dwyce Drive Austin, TX 78757 512.921.4224 cell sarah@bullockmcintyre.cc

PERMIT DRAWINGS

SITE PLAN